

NON-WARRANTY SERVICE PRICE LIST

Service prices below are estimates and subject to product inspection.

REGULATORS / VALVES (labor charge only, does not include parts)

- Complete Regulator (1st stage w/primary 2nd stage) \$40.00
- Additional 2nd stage (Octopus) \$15.00
- Airsource (Integrated Octopus) \$20.00

BUOYANCY COMPENSATORS (labor charge only, does not include parts)

- i3 System \$15.00
- B.C. with standard inflator \$15.00
- Inflator Airway only \$10.00
- Puncture Repair (1st patch, each additional \$10.00) \$20.00

SCUBA TANKS & VALVES (labor charge only, does not include parts)

- Tank Visual Inspection \$10.00
- Tank Valve Rebuild \$20.00
- Air Fill (3000psi) \$ 7.00

All products sent to Aqua Lung requiring testing or evaluation will be subject to a \$15.00 minimum charge, plus shipping costs.